



# MOLLE Clip Installation Instructions:

## STAR-PAN II

808-057-1



Remove and replace all six screws on the hub using the following:

Torque Value -  $32 \pm 8$  IN-OZ

Driver Size - .050" HEX