
MOLLE Clip Installation Instructions:

STAR-PAN IV

808-273



Remove and replace the two topmost screws, and the two screws second from the bottom using the following:

Torque Value - 32±8 IN-OZ

Driver Size - .050"HEX

Do not remove the remaining four screws in the middle portion of the hub, or the two bottommost screws.